

General Environmental Incident Summary

Incident: 1951 **Date/Time Notice:** 6/20/2013 11:00 **DEM Incident No:**

Responsible Party: Cased Hole Solutions

Date Incident: 6/19/2013 **Time Incident:** 21:00 **Duration:**

County: Mountrail **Twp:** 152 **Rng:** 91 **Sec:** 25 **Qtr:** SE SW

Lat: 47.95029 **Long:** -102.26620 **Method:** Navigation quality GPS

Location Description: 47.950292 North Latitude, 102.266241 West Longitude

Submitted By: Luigi Heydt

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person:

4946 HWY 85
Williston, ND

Distance Nearest Occupied Building:

Type of Incident: Hydraulic oil spill

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 1.25 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

A crane truck was backing up on location and did not see a hydraulic oil tank. When the truck struck the tank it punctured the tank spilling hydraulic oil on the ground.

Risk Evaluation:

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

The oil was removed from the ground using absorbant pads and the stained soil was scooped up using a loader.

Wastes Disposal Location: Unknown vendor will dispose of material

Agencies Involved: TAT Environmental

Updates

Date: 6/21/2013

Status: Reviewed; Followup Required

Staff: Roberts, Kris

Updated Volume:

Notes:

This may be an EOG location, given who is reporting the incident. Follow-up is indicated to ensure complete clean-up.

Date: 7/24/2013

Status: Reviewed; BIA/Tribal Lead

Staff: Stockdill, Scott

Updated Volume:

Notes:

Site located within MHA nation boundaries.

Spoke with Luigi Heydt at 2:49 7/1/2013 about spill. Luigi stated that the spill has been cleaned up using sorbent pads and excavation equipment.

All further issues will be forwarded to MHA environmental office.